

# Permanent Magnetic Lifter Operation Instructions



# Operatin instructions

1、 Main usage and characteristics	.....	1
2、 Main structure and parameters	.....	1
3、 The choice of the type	.....	2
4、 The operation and use	.....	3
5、 The maintence and safty	.....	4


## 1、 Main usage and characteristics

The permanent magnetic lifter of PML series is mainly used to magnetism plant shape or column ironware materials and workpiece, It is provided with the characteristics of light structure, easy operation, powerful magnetism, it has been widely used as the hoisting tool in factory, dock, storehouse and transportation.

## 2、 Main structure and parameters

The Nd-Fe-B high performance permanent magnetic material is used for the permanent magnetic crane, It can produce very strong magnetism within the magnetic circuit. The handle can be used to swith on or off the core shaft of the crane and free of power supply. When the crane is under working Status, the magnetism of the crane bottom will form a pair of longitudinal magnetic pole to firmly absorb the workpiece of iron material. There is a V shape groove on the attraction surface, so it can be used for both plank-shape workpiece and column-one.

### Main Technology Parameters



Type	Rated Lifting weight(kg)	Max pulling power(kg)	Dimension(mm)				Net weight (kg)
			L	B	H	R	
PML-100	100	350	94	72	78	145	3.2
PML-200	200	700	146	72	81	145	5.4
PML-300	300	1050	160	92	94	215	10
PML-400	400	1400	168	94	106	178	11
PML-600	600	2100	218	116	116	225	20
PML-1000	1000	3500	272	145	145	295	40
PML-2000	2000	6000	388	160	170	365	74
PML-3000	3000	9000	460	185	185	425	105
PML-5000	5000	15000	568	250	255	900	248

### 3 The choice of the type

According to the workpiece's thickness, weight, the gap of the workpiece and the permanent magnetic crane, material, the area of the attraction, the balance of the weight and the roughness degree of the surface, and then choose the relevant type.

#### 3.1 The conversion reference of the thickness and lifting power:

	( Steel plate thickness)		( Rate of the hoisting Capacity)						
	mm	inch	PML-50	PML-30	PML-20	PML-10	PML-6	PML-3	PML-1
T1	Up60	Up2.36	100%	100%	100%	100%	100%	100%	100%
T2	55	2.16"	90%	90%					
T3	50	1.97"	85%	85%	95%	100%	100%	100%	
T4	45	1.77"	80%	80%	85%				
T5	40	1.57"	75%	75%	80%	100%	100%	100%	
T6	35	1.38"	65%	65%	70%				
T7	30	1.18"	55%	55%	60%	75%	100%	100%	
T8	25	0.98"	45%	45%	50%	65%			
T9	20	0.79"	35%	35%	40%	55%	70%	85%	
T10	15	0.59"	25%	25%	30%	45%	55%	65%	
T11	10	0.39"	15%	15%	20%	30%	40%	45%	65%
T12	5	0.20"	10%	10%	10%	15%	20%	25%	35%

#### 3.2 The surface roughness of the material(Fx), the material(Mx)and the lifting power conversion,

The load capacity and the roughness of the surface,


	0	50%	100%	125%		0	50%	100%
F1	1.6 μm		125%		M1	(Low carbon steel)		100%
F2	6.3 μm		100%		M2	(Inside carbon steel)		90%
F3	12.6 μm		90%		M3	(High carbon steel)		80%
F4	~		80%		M4	(Low metal alloy steel)		70%
					M5	(Cast iron)		50%

#### 3.3 The conversion formula of the lifting range—(Tx\*Fx\*Mx\*rated lifting weight Kg)

3.4 For example: material condition: T8 , F1, M3, 1000Kg(PML-1000)

#### 4 The operation and use

##### 4.1 Install method, as the picture,



4.2 The workpiece's material, thickness, quality of surface will influence the lifting power, therefore, before operation, should according to the practical situation, Tx and lifting power conversion, Fx, Mx and lifting power conversion and then estimate the crane's lifting power, and then decide the actual hoisting capacity.

4.3 The lifting power of the permanent magnetic crane in relation to the attracting area, when in using, try best to make the area largest.

4.4 The handle operate power has relation with the using degree of the crane's lifting capacity, such as lift a column workpiece, thin workpiece, the surface roughness above 6.3um, or worse with smaller attraction area, the handle operate power will be aggrandizement.

##### 4.5 Working environment condition of the permanent magnetic crane.

A. The temperature is not higher than 80°C

B. No violent shake or impact.

C. No metal erosion metal agent around the environment.


4.6 When hoisting workpiece, be sure to hoist the gravity center of the workpiece to guarantee the balance, then switch the handle from OFF to ON, and confirm that the slide—key of the handle is

locked and then begin hoisting, the crane should move smoothly to avoid shake that may cause workpiece drop and accident.

4.7 If it is used to hoist column-shape workpiece, please be sure to make the V-shape on the crane bottom contact with the workpiece, but the hoisting capacity is only 30%–50% of the rated hoisting capacity. (the decrease of hoisting capacity related the diameter the column workpiece)

4.8 After hoisting operation, please detach the slide-key of the handle from the positioning lock, then recover the handle to the free position shut off and take down the crane.

4.9 Should consider the core when lifting the long shape workpiece, the length should not above 3000mm in principle, or use more crane, as picture.



5. The maintenance and safety

5.1 The idle load of the permanent magnetic crane is forbidden.

5.2 The permanent magnetic crane must work within the rated weight. It is forbidden for over loading to avoid accident.

5.3 It is forbidden to stand under or through the hoisted workpiece during operation

5.4 When in operation, after the workpiece is in the air, then can start the moving work.

5.5 Do not turn the handle when the crane bottom haven't magnetism workpiece.

5.6 Please check the slide-key and positioning-bolt regularly to guarantee reliable lock and safety.

5.7 Keep the absorbing surface clean and flat and remove the impurity

5.8 Do not strike and impact the permanent magnetic crane during operation, these may influence its performance.

5.9 Please demarcate and test the crane every two years after putting into use to ensure safety.